

**Coffey Environments Risk Assessment**

Asbestos Fibre Type	Surface Treatment	Product Type	Extent of Damage / Deterioration	Likelihood of Disturbance (Potential for Fibre Release)
0 NAD (No Asbestos Detected)	0 Composite materials, vinyl floor tiles,	0 NAD (No Asbestos Detected)	0 No visible damage	0 Usually inaccessible/unlikely to be disturbed
1 Chrysotile	1 Enclosed laggings/sprays, sealed low density board, cement sheets	1 Composites, vinyl floor tiles, reinforced plastics, mastics & resins, cements, paints	1 Few scratches / marks, broken edges	1 Occasionally likely to be disturbed
2 Amphibole (Excluding Crocidolite)	2 Unsealed low density board, sealed lagging/spray,	2 Low density boards, millboard, textiles, rope, paper, felts	2 Significant breakage / areas of damage revealing fibres	2 Easily disturbed
3 Crocidolite	3 Unsealed thermal insulation/laggings/sprays	3 Thermal insulation, lagging, spray coatings, mattresses & packing, residues / debris	3 High damage, visible debris	3 Routinely disturbed

  

Risk Score	Action Ratings	Inspection Type
2 - 4 Very Low Risk	A1 Restrict access, manage and remove under fully controlled conditions	Type 1 Visual Assessment
5 - 7 Low Risk	A2 Restrict access, manage and remove utilising appropriate control measures	Type 2 Compliance Survey (as required by [NOHSC:2018 (2005)])
8 - 11 Medium Risk	A3 Program for planned removal, manage and re-inspect periodically	Type 3 Intrusive Sampling Survey
12 - 15 High risk	A4 Enclose, encapsulate or seal, manage and re-inspect periodically	Type 3* Partial Intrusive Sampling Survey Limited to Scope
	A5 Manage and re-inspect periodically	

GROUP (AREA/ SUBURB)	ADDRESS 1	SITE ID (Maximo Ref)	KNOWN AS	Site Ref	SAMPLE DESCRIPTION	SAMPLE LOCATION	Coffey Environments Risk Assessment							Asbestos Management					
							Asbestos Fibre Type	Surface Treatment	Product Type	Condition	Likelihood of Disturbance	Risk Score	Action Rating	Inspection Date	Asbestos Consultant	Report Reference Number	Inspection Type	Labelled Y/N	Re-inspection Due (as required by [NOHSC:2018 (2005)])
Basin	Kingsway	THBA-WWTPT	Waste Water Treatment Plant	N	Molded fibre cement pipes protruding from tank.	Protruding from IMHOFF Tank.	1	1	1	2	2	7	A3	17/11/2017	Programmed Facility Management				Nov-20
Bathurst	505 Raven Road	BATH-UN505	Unit 505	N	Fibre cement ceiling linings	Front and rear verandahs	2	1	1	0	0	4	A4	17/10/2017	Coffey Environments	ENAUPEI02892AA	2		Oct-18
Bathurst	507 Raven Road	BATH-UN507	Unit 507	N	Fibre cement ceiling lining	Throughout Units	2	1	1	0	0	4	A4	17/10/2017	Coffey Environments	ENAUPEI02892AA	2		Oct-18
Bathurst	507 Raven Road	BATH-UN507	Unit 507	N	Fibre cement eaves, gable and verandah ceiling linings	Perimeter of Units	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPEI02892AA	2		Nov-20
Bathurst	508 Raven Road	BATH-UN508	Unit 508	N	Fibre cement ceiling lining	Throughout Units	2	1	1	0	0	4	A4	17/10/2017	Coffey Environments	ENAUPEI02892AA	2		Oct-18
Bathurst	508 Raven Road	BATH-UN508	Unit 508	N	Fibre cement eaves, gable and verandah ceiling linings	Perimeter of Units	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPEI02892AA	2		Nov-20
Bathurst	511 Transit Road	BATH-UN511	Unit 511	N	Fibre cement eaves and verandah ceiling lining	Front and rear of Units	1	1	1	2	0	5	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPEI02892AA	2		Nov-20
Bathurst	511 Transit Road	BATH-UN511	Unit 511	N	Fibre cement ceiling lining	Throughout Units	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPEI02892AA	2		Oct-18
Bathurst	514 Transit Road	BATH-UN514	Unit 514	N	Fibre cement eaves and verandah ceiling lining	Front and rear of Units	1	1	1	2	0	5	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPEI02892AA	2		Nov-20
Bathurst	514 Transit Road	BATH-UN514	Unit 514	N	Fibre cement ceiling lining	Throughout Units	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPEI02892AA	2		Oct-18
Bathurst	516 Transit Road	BATH-UN516	Unit 516	N	Fibre cement eaves and verandah ceiling lining	Front and rear of Units	1	1	1	2	0	5	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPEI02892AA	2		Nov-20
Bathurst	516 Transit Road	BATH-UN516	Unit 516	N	Fibre cement ceiling lining	Throughout Units	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPEI02892AA	2		Oct-18
Bathurst	517 Transit Road	BATH-UN517	Unit 517	N	Fibre cement eaves and verandah ceiling lining	Front and rear of Units	1	1	1	2	0	5	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPEI02892AA	2		Nov-20
Bathurst	517 Transit Road	BATH-UN517	Unit 517	N	gable end panels	Roof of Units	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPEI02892AA	1		Nov-20
Bathurst	517 Transit Road	BATH-UN517	Unit 517	N	Fibre cement ceiling lining	Throughout Units	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPEI02892AA	2		Oct-18
Bathurst	518 Transit Road	BATH-UN518	Unit 518	N	gable end panels	Roof of Units	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPEI02892AA	1		Nov-20
Bathurst	518 Transit Road	BATH-UN518	Unit 518	N	Fibre cement ceiling lining	Throughout Units	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPEI02892AA	2		Oct-18
Bathurst	521 Transit Road	BATH-UN521	Unit 521	N	gable end panels	Roof of Units	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPEI02892AA	1		Nov-20
Bathurst	521 Transit Road	BATH-UN521	Unit 521	N	Fibre cement ceiling lining	Throughout Units	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPEI02892AA	2		Oct-18
Bathurst	524 Transit Road	BATH-UN524	Unit 524	N	Fibre cement ceiling lining	Throughout Units	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPEI02892AA	2		Oct-18
Bathurst	526 Lancier Street	BATH-UN526	Unit 526	N	Fibre cement ceiling lining	Throughout Units	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPEI02892AA	2		Oct-18
Bathurst	526 Lancier Street	BATH-UN526	Unit 526	N	Fibre cement eaves and verandah ceiling lining	Front and rear of Units	1	1	1	0	0	3	A5	25/11/2017	Coffey Environments-Geri Treolar	ENAUPEI02892AA	2		Nov-20
Bathurst	530 Lancier Street	BATH-UN530	Unit 530	N	Fibre cement ceiling lining	Throughout Units	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPEI02892AA	2		Oct-18
Bathurst	530 Lancier Street	BATH-UN530	Unit 530	N	Fibre cement eaves and verandah ceiling lining	Front and rear of Units	1	1	1	0	0	3	A5	25/11/2017	Coffey Environments-Geri Treolar	ENAUPEI02892AA	2		Nov-20
Bathurst	532 Lancier Street	BATH-UN532	Unit 532	N	Fibre cement ceiling lining	Throughout Units	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPEI02892AA	2		Oct-18
Bathurst	532 Lancier Street	BATH-UN532	Unit 532	N	Fibre cement eaves and verandah ceiling lining	Front and rear of Units	1	1	1	0	0	3	A5	25/11/2017	Coffey Environments-Geri Treolar	ENAUPEI02892AA	2		Nov-20
Bathurst	534 Lancier Street	BATH-UN534	Unit 534	N	Fibre cement ceiling lining	Throughout Units	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPEI02892AA	2		Oct-18
Bathurst	534 Lancier Street	BATH-UN534	Unit 534	N	Fibre cement eaves and verandah ceiling lining	Front and rear of Units	1	1	1	0	0	3	A5	25/11/2017	Coffey Environments-Geri Treolar	ENAUPEI02892AA	2		Nov-20
Bathurst	535 Gem Road	BATH-UN535	Alpen 1 Cottage	N	Fibre cement ceiling lining	Throughout cottage	2	1	1	0	0	4	A4	17/10/2017	Coffey Environments	ENAUPEI02892AA	2		Oct-18
Bathurst	535 Gem Road	BATH-UN535	Alpen 1 Cottage	N	Fibre cement wall lining	Cottage additions	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPEI02892AA	2		Nov-20
Bathurst	547 Gem Street	BATH-UN547	Bathurst Lighthouse Caretakers Cottage	N	Fibre cement ceiling lining	Verandah	2	1	1	0	0	4	A4	17/10/2017	Coffey Environments	ENAUPEI02892AA	2		Oct-18
Bathurst	547 Gem Street	BATH-UN547	Bathurst Lighthouse Caretakers Cottage	N	Molded fibre cement cable pit	West side entry	2	1	1	1	1	6	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPEI02892AA	2		Nov-20

GROUP (AREA/ SUBURB)	ADDRESS 1	SITE ID (Maximo Ref)	KNOWN AS	Site Ref	SAMPLE DESCRIPTION	SAMPLE LOCATION	Coffey Environments Risk Assessment							Asbestos Management					
							Asbestos Fibre Type	Surface Treatment	Product Type	Condition	Likelihood of Disturbance	Risk Score	Action Rating	Inspection Date	Asbestos Consultant	Report Reference Number	Inspection Type	Labelled Y/N	Re-inspection Due (as required by [NOHSC:2018 (2005)])
Bathurst	547 Gem Street	BATH-UN547	Bathurst Lighthouse Caretakers Cottage	N	Molded fibre cement pipe in ground	Rear gate on west side	1	1	1	1	1	5	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Bathurst	548 Gem Street	BATH-UN548	Bathurst Lighthouse Caretakers Cottage	N	Fibre cement ceiling lining	Verandah	2	1	1	0	0	4	A4	17/10/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Oct-18
Bathurst	548 Gem Street	BATH-UN548	Bathurst Lighthouse Caretakers Cottage	N	Molded fibre cement cable pit	West side entry	2	1	1	1	1	6	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Bathurst	548 Gem Street	BATH-UN548	Bathurst Lighthouse Caretakers Cottage	N	Molded fibre cement pipe in ground	Rear gate on west side	1	1	1	1	1	5	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Geordie Bay	Water Catchment Site	GEBA-T4PHS	Pump House	N	Corrugated fibre cement sheeting	Roof of building	3	2	1	1	1	8	A3	20/09/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Sep-20
Geordie Bay	Water Catchment Site	GEBA-T4PHS	Pump House	N	Molded fibre cement capping	Roof of building	2	3	1	1	1	8	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Geordie Bay	Water Catchment Site	GEBA-T4PHS	Pump House	N	Waterproof membrane to the overflow pipe	From Main Water Tank	1	1	1	1	1	5	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Geordie Bay	Water Catchment Site	GEBA-T4PHS	Pump House	N	Molded fibre cement pipe work partially exposed above ground	North side of Tank	1	1	1	1	1	5	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Geordie Bay	Water Catchment Site	GEBA-T4PHS	Pump House	N	Broken molded fibre cement pipe work (x3) going underground outside fenced	South west corner	1	1	1	1	1	5	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Geordie Bay	Water Catchment Site	GEBA-T4PHS	Tank 4	N	Grey compressed fibre cement material	Surrounding boundary	3	1	1	3	1	9	A3	16/02/2018	Apollo Inspectorate	585479-AID	2		Feb-19
Kingstown	555 UWA House	KING-555UH	Airport House	N	Fibre cement wall and ceiling lining	Front and rear Sleep outs, west side of building	1	1	1	2	0	5	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown	555 UWA House	KING-555UH	Airport House	N	Corrugated fibre cement fence	Rear and side boundaries	1	1	1	1	1	5	A4	17/10/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Oct-18
Kingstown	Adjacent D.I.D. Shed	KING-PHUTT	'P' Hut	N	Fibre cement ceiling lining	Throughout shed	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Oct-18
Kingstown	Adjacent D.I.D. Shed	KING-PHUTT	'P' Hut	N	Perforated fibre cement ceiling lining	Throughout shed	1	1	1	0	0	3	A5	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown	Bickley Battery	TBA	Gun Station No.2	N	Molded fibre cement pipe sleeve	Through wall	1	1	1	2	0	5	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown	Bickley Battery (near Parker Point Road)	TBA	F1 Magazine	N	Molded fibre cement pipe exposed in ground	Kingstown end of air strip, intersection of fire break	1	1	1	2	1	6	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown	Old Tank farm	KING-TBA	Old Tank Farm	N	Fibre cement debris	Surrounding boundary	1	1	1	2	0	5	A4	16/02/2018	Apollo Inspectorate	585487-AID	2		Feb-21
Kingstown	TBA	TBA	Old Railway Area - Workshops	N	Fibre cement wall lining	Gymnasium area	1	1	1	0	0	3	A5	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	17 Kingstown Road	KING-17KIR	Residence 17	N	Fibre Cement wall cladding	Front, sides and rear (west only)	1	1	1	0	1	4	A4	1/04/2016	PR-PFM	PFM	2		
Kingstown Barracks	17 Kingstown Road	KING-17KIR	Residence 17	N	Fibre cement ceiling lining	Bedrooms and bathroom	0	1	1	0	1	3	A4	1/04/2016	PR-PFM	PFM	2		
Kingstown Barracks	17 Kingstown Road	KING-17KIR	Residence 17	N	Fibre cement wall lining	3/4 to bottom in bathroom	0	1	1	0	1	3	A4	1/04/2016	PR-PFM	PFM	2		
Kingstown Barracks	17 Kingstown Road	KING-17KIR	Residence 17	N	Fibre cement wall lining	Upper half of wall lining in Sleep Out	0	1	1	0	1	3	A4	1/04/2016	PR-PFM	PFM	2		
Kingstown Barracks	17 Kingstown Road	KING-17KIR	Residence 17	N	Fibre cement wall lining	Behind sink in Sleep Out	0	1	1	0	1	3	A4	1/04/2016	PR-PFM	PFM	2		
Kingstown Barracks	17 Kingstown Road	KING-17KIR	Residence 17	N	Fibre cement ceiling and wall linings	Throughout	2	1	1	0	0	4	A4	17/10/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Oct-18
Kingstown Barracks	17 Kingstown Road	KING-17KIR	Residence 17	N	Fibre cement external wall cladding	Perimeter of building	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Oct-18
Kingstown Barracks	2 Kingstown Road	KING-UN150	Unit 150 - Commander's Cottage	N	Fibre cement ceiling and wall lining	Throughout cottage	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	2 Kingstown Road	KING-UN150	Unit 150 - Commander's Cottage	N	Fibre cement external wall cladding	Perimeter of cottage	1	1	1	0	0	3	A5	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	2 Kingstown Road	KING-UN150	Unit 150 - Commander's Cottage	N	Fibre cement eaves lining	East and west sides of cottage and Laundry	1	1	1	0	0	3	A5	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	4 Kingstown Road	KING-PEINN	Peacock Inn	N	Fibre cement external wall cladding	Perimeter of building	1	1	1	0	0	3	A5	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	4 Kingstown Road	KING-PEINN	Peacock Inn	N	Fibre cement eaves ceiling lining	Perimeter and front Porch	1	1	1	0	0	3	A5	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	5 Kingstown Road	KING-UN109	Unit 109 - Sargent's Mess	N	Molded fibre cement cable pit	Rear of building	2	1	1	2	1	7	A3	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	5 Kingstown Road	KING-UN109	Unit 109 - Sargent's Mess	N	Fibre cement ceiling lining	Throughout building	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Oct-18
Kingstown Barracks	5 Kingstown Road	KING-UN109	Unit 109 - Sargent's Mess	N	Fibre cement external wall cladding and infill panels	Front Verandah	1	1	1	0	0	3	A5	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	6 Kingstown Road	KING-UN152	Unit 152 - Cottage	N	Fibre cement ceiling and wall lining	Throughout cottage	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	6 Kingstown Road	KING-UN152	Unit 152 - Cottage	N	Fibre cement external wall cladding	Perimeter of cottage	1	1	1	0	0	3	A5	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	6 Kingstown Road	KING-UN152	Unit 152 - Cottage	N	Fibre cement eaves lining	East and west sides of cottage and Laundry	1	1	1	0	0	3	A5	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	7 Kingstown Road	KING-UN101	Unit 101 - Stirling Cottage	N	Fibre cement external wall cladding	Perimeter of cottage	1	1	1	1	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	7 Kingstown Road	KING-UN101	Unit 101 - Stirling Cottage	N	Fibre cement ceiling and wall lining	Throughout cottage	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	7 Kingstown Road	KING-UN102	Unit 102 - Hutt Cottage	N	Fibre cement external wall cladding	Perimeter of cottage	1	1	1	1	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	7 Kingstown Road	KING-UN102	Unit 102 - Hutt Cottage	N	Fibre cement ceiling and wall lining	Throughout cottage	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	7 Kingstown Road	KING-UN103	Unit 103 - Clarke Cottage	N	Fibre cement eaves lining	Perimeter of cottage and adjoining Laundry building	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	7 Kingstown Road	KING-UN103	Unit 103 - Clarke Cottage	N	Fibre cement ceiling and wall lining	Throughout cottage	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20

GROUP (AREA/ SUBURB)	ADDRESS 1	SITE ID (Maximo Ref)	KNOWN AS	Site Ref	SAMPLE DESCRIPTION	SAMPLE LOCATION	Coffey Environments Risk Assessment							Asbestos Management					
							Asbestos Fibre Type	Surface Treatment	Product Type	Condition	Likelihood of Disturbance	Risk Score	Action Rating	Inspection Date	Asbestos Consultant	Report Reference Number	Inspection Type	Labelled Y/N	Re-inspection Due (as required by [NOHSC:2018 (2005)])
Kingstown Barracks	7 Kingstown Road	KING-UN103	Unit 103 - Clarke Cottage	N	Fibre cement external wall cladding	Perimeter of cottage	1	1	1	0	0	3	A5	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	7 Kingstown Road	KING-UN104	Unit 104 - Irwin Cottage	N	Fibre cement external wall cladding	Perimeter of cottage	1	1	1	1	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	7 Kingstown Road	KING-UN104	Unit 104 - Irwin Cottage	N	Fibre cement ceiling and wall lining	Throughout cottage	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	7 Kingstown Road	KING-UN105	Unit 105 - Fitzgerald Cottage	N	Fibre cement external wall cladding	Perimeter of cottage	1	1	1	1	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	7 Kingstown Road	KING-UN105	Unit 105 - Fitzgerald Cottage	N	Fibre cement eaves lining	Perimeter of cottage and adjoining Laundry building	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	7 Kingstown Road	KING-UN105	Unit 105 - Fitzgerald Cottage	N	Fibre cement ceiling and wall lining	Throughout cottage	2	1	1	1	0	5	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	7 Kingstown Road	KING-UN106	Unit 106 - Kennedy Cottage	N	Fibre cement external wall cladding	Perimeter of cottage	1	1	1	1	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	7 Kingstown Road	KING-UN106	Unit 106 - Kennedy Cottage	N	Fibre cement eaves lining	Perimeter of cottage and adjoining Laundry building	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	7 Kingstown Road	KING-UN106	Unit 106 - Kennedy Cottage	N	Fibre cement ceiling and wall lining	Throughout cottage	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	7 Kingstown Road	KING-UN107	Unit 107 - Hampton Cottage	N	Fibre cement eaves lining	Perimeter of cottage and adjoining Laundry building	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	7 Kingstown Road	KING-UN107	Unit 107 - Hampton Cottage	N	Fibre cement ceiling and wall lining	Throughout cottage	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	7 Kingstown Road	KING-UN107	Unit 107 - Hampton Cottage	N	Fibre cement external wall cladding	Perimeter of cottage	1	1	1	0	0	3	A5	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	7 Kingstown Road	KING-UN108	Unit 108 - Weld Cottage	N	Asbestos cement wedged in low level wood fencing	Pathway between units 108 and 109	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	02892AA	1		Sep-20
Kingstown Barracks	7 Kingstown Road	KING-UN108	Unit 108 - Weld Cottage	N	Fibre cement external wall cladding	Perimeter of cottage	1	1	1	1	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	7 Kingstown Road	KING-UN108	Unit 108 - Weld Cottage	N	Fibre cement eaves lining	Perimeter of cottage and adjoining Laundry building	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	7 Kingstown Road	KING-UN108	Unit 108 - Weld Cottage	N	Fibre cement ceiling and wall lining	Throughout cottage	2	1	1	1	0	5	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	Battery Road	KING-BARCK	Main Dormitory Building (old Barracks)	N	Fibre cement ceiling lining	Throughout building	2	1	1	0	0	4	A4	17/10/2017	Coffey Environments	02892AA	2		Oct-18
Kingstown Barracks	Battery Road	KING-BARCK	Main Dormitory Building (old Barracks)	N	Fibre cement shingles (panels)	West side gable, north and south skylights to Kitchen	1	1	1	0	0	3	A5	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	Battery Road	KING-BARCK	Main Dormitory Building (old Barracks)	N	Fibre cement eaves and verandah ceiling lining	Perimeter of building	1	1	1	0	0	3	A5	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	Governors Circuit	KING-DISCT	Discovery Centre	N	Profiled fibre cement external wall cladding	Perimeter of building	2	1	1	1	1	6	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	Governors Circuit	KING-DISCT	Discovery Centre	N	Fibre cement ceiling and wall lining	Throughout building	2	1	1	1	0	5	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	Hospital Lane	KING-RAEBL	Administration Office & Youth Hostel (RAF)	N	Fibre cement ceiling lining	Throughout building	2	0	0	0	0	2	A5	9/10/2017	Apollo Inspectorate	AIP17109.008	2		Oct-20
Kingstown Barracks	Hospital Lane	KING-RAEBL	Administration Office & Youth Hostel (RAF)	N	Fibre cement eaves and verandah lining	Perimeter of building	1	1	1	0	0	3	A5	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	Hospital Lane	KING-RAEBL	Floor void below Kitchen	N	Asbestos fibre cement packing material	Throughout the basement void and used as packing	2	0	0	0	0	2	A5	9/10/2017	Apollo Inspectorate	AIP17109.008	2	Y	Oct-20
Kingstown Barracks	Hospital Lane	KING-RAEBL	Hostel Toilets & Showers	N	Profiled fibre cement external wall cladding	Both ends of building	2	1	1	1	0	5	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	Hospital Lane	KING-RAEBL	Hostel Toilets & Showers	N	Fibre cement ceiling and wall lining	Throughout building	2	1	1	1	0	5	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	Kingstown Road	KING-RAABL	Youth Hostel (RAA)	N	Fibre cement ceiling lining	Throughout building	2	1	1	0	0	4	A4	14/11/2017	PFM - J.Wright	572601-AID	2		Nov-20
Kingstown Barracks	Kingstown Road	KING-RAABL	Youth Hostel (RAA)	N	Fibre cement eaves and verandah lining	Perimeter of building	1	1	1	0	0	3	A5	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	Kingstown Road	KING-RAABL	Youth Hostel (RAA)	N	Panels to external of fire door	Fire exit door, adjacent road	1	1	1	0	0	3	A5	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	Kingstown Road	KING-TOLND	Laundry & Public Toilets	N	Fibre cement ceiling lining	Throughout	2	1	1	0	0	4	A4	17/10/2017	Coffey Environments	02892AA	2		Oct-18
Kingstown Barracks	Unit 153 Kingstown Road	KING-UN153	CEO Cottage, Unit 153.	N	Fibre cement ceiling and wall lining	Throughout cottage	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	Unit 153 Kingstown Road	KING-UN153	CEO Cottage, Unit 153.	N	Fibre cement external wall cladding	Perimeter of cottage	1	1	1	0	0	3	A5	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Kingstown Barracks	Unit 153 Kingstown Road	KING-UN153	CEO Cottage, Unit 153.	N	Fibre cement eaves lining	East and west sides of cottage and Laundry	1	1	1	0	0	3	A5	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	801 Zephyr Road	LGRH-UN801	Unit 801	N	Molded Cement Cable Pit	Adjacent Unit 801	3	1	1	1	1	7	A3	20/09/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	1		Sep-20
Longreach Bay	801 Zephyr Road	LGRH-UN801	Unit 801	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	802 Zephyr Road	LGRH-UN802	Unit 802	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	803 Zephyr Road	LGRH-UN803	Unit 803	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	804 Zephyr Road	LGRH-UN804	Unit 804	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	805 Zephyr Road	LGRH-UN805	Unit 805	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	806 Zephyr Road	LGRH-UN806	Unit 806	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	807 Zephyr Road	LGRH-UN807	Unit 807	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	808 Zephyr Road	LGRH-UN808	Unit 808	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20

GROUP (AREA/ SUBURB)	ADDRESS 1	SITE ID (Maximo Ref)	KNOWN AS	Site Ref	SAMPLE DESCRIPTION	SAMPLE LOCATION	Coffey Environments Risk Assessment							Asbestos Management					
							Asbestos Fibre Type	Surface Treatment	Product Type	Condition	Likelihood of Disturbance	Risk Score	Action Rating	Inspection Date	Asbestos Consultant	Report Reference Number	Inspection Type	Labelled Y/N	Re-inspection Due (as required by [NOHSC:2018 (2005)])
Longreach Bay	809 Zephyr Road	LGRH-UN809	Unit 809	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	810 Zephyr Road	LGRH-UN810	Unit 810	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	811 Zephyr Road	LGRH-UN811	Unit 811	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	812 Zephyr Road	LGRH-UN812	Unit 812	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	813 Zephyr Road	LGRH-UN813	Unit 813	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	814 Zephyr Road	LGRH-UN814	Unit 814	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	815 Zephyr Road	LGRH-UN815	Unit 815	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	816 Zephyr Road	LGRH-UN816	Unit 816	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	817 Zephyr Road	LGRH-UN817	Unit 817	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	818 Zephyr Road	LGRH-UN818	Unit 818	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	819 Zephyr Road	LGRH-UN819	Unit 819	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	820 Zephyr Road	LGRH-UN820	Units 820	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	821 Zephyr Road	LGRH-UN821	Units 821	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	822 Zephyr Road	LGRH-UN822	Units 822	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	823 Zephyr Road	LGRH-UN823	Units 823	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	824 Zephyr Road	LGRH-UN824	Units 824	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	825 Zephyr Road	LGRH-UN825	Units 825	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	826 Zephyr Road	LGRH-UN826	Units 826	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	827 Zephyr Road	LGRH-UN827	Units 827	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	828 Zephyr Road	LGRH-UN828	Units 828	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	829 Zephyr Road	LGRH-UN829	Units 829	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	830 Zephyr Road	LGRH-UN830	Units 830	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	831 Zephyr Road	LGRH-UN831	Units 831	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	832 Zephyr Road	LGRH-UN832	Units 832	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	833 Zephyr Road	LGRH-UN833	Units 833	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	834 Zephyr Road	LGRH-UN834	Units 834	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	835 Zephyr Road	LGRH-UN835	Units 835	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Longreach Bay	836 Zephyr Road	LGRH-UN836	Units 836	N	Molded fibre cement flue pipe	Internally & on roof	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Oliver Hill	Tunnels	OLHI-OHTNL	Below ground	N	molded fibre cement pipes	To ventilation shafts	2	1	1	0	0	4	A4	17/10/2017	Coffey Environments	ENAUPERT 02892AA	1		Oct-18
Thomson Bay Central	11 Sommerville Drive	TBCE-11SDR	Unit 11	N	Fibre cement external wall cladding	Perimeter of Unit	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPERT 02892AA	2		Oct-18
Thomson Bay Central	12 Kelly Street	TBCE-12KST	School Principals Cottage	N	Fibre cement eaves lining	Perimeter of Cottage	2	1	1	0	0	4	A4	17/10/2017	Coffey Environments	ENAUPERT 02892AA	2		Oct-18
Thomson Bay Central	12 Kelly Street	TBCE-12KST	School Principals Cottage	N	Molded fibre cement fence capping	North, west and east boundaries	2	1	1	1	1	6	A4	17/10/2017	Coffey Environments	ENAUPERT 02892AA	2		Oct-18
Thomson Bay Central	12 Kelly Street	TBCE-12KST	School Principals Cottage	N	Corrugated fibre cement fence	North, west and east boundaries	2	1	1	1	1	6	A4	17/10/2017	Coffey Environments	ENAUPERT 02892AA	2		Oct-18
Thomson Bay Central	14 Kelly Street	TBCE-14KST	Primary School	N	Fibre cement eaves ling	Perimeter of school	2	1	1	1	0	5	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Thomson Bay Central	2 Bedford Street	TBSO-RIAEO	Executive Office	N	Corrugated fibre cement fence	Rear property boundary	2	1	1	1	1	6	A4	17/10/2017	Coffey Environments	ENAUPERT 02892AA	2		Oct-18
Thomson Bay Central	2 Bedford Street	TBSO-RIAEO	Executive Office	N	Molded fibre cement fence capping	Rear property boundary	2	1	1	1	1	6	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Thomson Bay Central	2 Stables Road	TBCE-2STRD	Salt Lakes Cottage	N	Molded fibre cement cable pit used as planter	Rear garden	3	1	1	1	2	8	A3	20/09/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Sep-20
Thomson Bay Central	2 Stables Road	TBCE-2STRD	Salt Lakes Cottage	N	Small corrugated fibre cement external wall cladding	Rear section of Cottage	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay Central	301 Vincent Way	TBNO-UN301	Unit 301	N	Fibre cement eaves and porch ceiling lining	To Unit	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Thomson Bay Central	301 Vincent Way	TBNO-UN301	Unit 301	N	Molded fibre cement cable pit	Adjacent front gate	2	1	1	1	1	6	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Thomson Bay Central	317 Vincent Way	TBNO-UN317	Unit 317	N	Fibre cement ceiling lining	Kitchen ceiling around exhaust fan	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPERT 02892AA	2		Oct-18

GROUP (AREA/ SUBURB)	ADDRESS 1	SITE ID (Maximo Ref)	KNOWN AS	Site Ref	SAMPLE DESCRIPTION	SAMPLE LOCATION	Coffey Environments Risk Assessment							Asbestos Management					
							Asbestos Fibre Type	Surface Treatment	Product Type	Condition	Likelihood of Disturbance	Risk Score	Action Rating	Inspection Date	Asbestos Consultant	Report Reference Number	Inspection Type	Labelled Y/N	Re-inspection Due (as required by [NOHSC:2018 (2005)])
Thomson Bay Central	318 Vincent Way	TBNO-UN318	Unit 318	N	Molded fibre cement vent pipe	Rear of Units	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments- Geri Treolar	ENAUPTERT 02892AA	2		Nov-20
Thomson Bay Central	320 Vincent Way	TBNO-UN320	Unit 320	N	Fibre cement ceiling lining	Kitchen	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	1		Oct-18
Thomson Bay Central	321 Vincent Way	TBNO-UN321	Unit 321	N	Molded fibre cement vent pipe	Rear of Units	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments- Geri Treolar	ENAUPTERT 02892AA	2		Nov-20
Thomson Bay Central	327 Vincent Way	TBNO-UN327	Unit 327	N	Fibre cement ceiling lining	Kitchen	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	1		Oct-18
Thomson Bay Central	328 Vincent Way	TBNO-UN328	Unit 328	N	Fibre cement ceiling lining	Kitchen	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	1		Oct-18
Thomson Bay Central	329 Vincent Way	TBNO-UN329	Unit 329	N	Fibre cement eaves and verandah ceiling lining	Perimeter of Unit	3	1	1	1	0	6	A4	20/09/2017	Coffey Environments	ENAUPTERT 02892AA	2		Sep-20
Thomson Bay Central	329 Vincent Way	TBNO-UN329	Unit 329	N	Fibre cement ceiling lining	Throughout Unit	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPTERT 02892AA	2		Sep-20
Thomson Bay Central	330 Vincent Way	TBNO-UN330	Unit 330	N	Fibre cement ceiling lining	Kitchen	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	1		Oct-18
Thomson Bay Central	345 Vincent Way	TBNO-UN345	Unit 345	N	Surface dust	Ceiling void in bedroom 4	1	2	3	3	1	10	A2	25/05/2017	Parry	Apollo 5589	3		Sep-18
Thomson Bay Central	4 Kitson Street	TBCE-4AKIT	The Lodge	N	Fibre cement ceiling linings and skylights	To Walkways Palm Court area	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay Central	4 Kitson Street	TBCE-4AKIT	The Lodge	N	Fibre cement infill panels	Gable ends throughout Lodge	1	1	1	0	0	3	A5	25/11/2017	Coffey Environments- Geri Treolar	ENAUPTERT 02892AA	2		Nov-20
Thomson Bay Central	4A Kitson Street	TBCE-4AKIT	Unit	N	Corrugated fibre cement fence	North boundary	1	1	1	3	1	7	A3	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay Central	4A Kitson Street	TBCE-4AKIT	Unit	N	Fibre cement ceiling linings	Kitchen, Dining and Bathroom	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay North	1 Mapleson Road	TBNO-SPSOF	Cleaners Office, Spotless Office	N	Corrugated fibre cement fence	At rear	2	1	1	2	1	7	A3	25/11/2017	Coffey Environments- Geri Treolar	ENAUPTERT 02892AA	2		Nov-20
Thomson Bay North	1 Mapleson Road	TBNO-SPSOF	Cleaners Office, Spotless Office	N	Fibre cement wall and ceiling lining	Rear Rooms	1	1	1	5	5	13	A2	25/11/2017	Coffey Environments- Geri Treolar	ENAUPTERT 02892AA	2		Sep-18
Thomson Bay North	1 Mapleson Road	TBNO-SPSOF	Cleaners Office, Spotless Office	N	Fibre cement wall lining	Toilet addition	3	1	1	1	0	6	A4	20/09/2017	Coffey Environments	ENAUPTERT 02892AA	2		Sep-20
Thomson Bay North	1 Mapleson Road	TBNO-SPSOF	Cleaners Office, Spotless Office	N	Fibre cement external wall cladding	Perimeter of Cottage	1	1	1	1	0	4	A4	25/11/2017	Coffey Environments- Geri Treolar	ENAUPTERT 02892AA	2		Nov-20
Thomson Bay North	1 Mapleson Road	TBNO-SPSOF	Cleaners Office, Spotless Office	N	Fibre cement wall and ceiling lining	Verandah	1	1	1	1	0	4	A4	25/11/2017	Coffey Environments- Geri Treolar	ENAUPTERT 02892AA	2		Nov-20
Thomson Bay North	10 Bovell Highway	TBNO-10BVW	Lodge Cottage (Big House)	N	Fibre cement external wall cladding, eaves and verandah ceiling lining	Perimeter of cottage	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPTERT 02892AA	2		Sep-20
Thomson Bay North	10 Bovell Highway	TBNO-10BVW	Lodge Cottage (Big House)	N	Laminated fibre cement wall lining	Both Toilets and Bathrooms & Laundry	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay North	10 Bovell Highway	TBNO-10BVW	Lodge Cottage (Big House)	N	Membrane beneath vinyl floor tiles	Kitchen	1	0	1	0	0	2	A5	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay North	10 Mapleson Road	TBNO-POSTN	Police Station	N	Fibre cement ceiling lining	Front entrance of Station	2	1	1	0	0	4	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay North	12 Boreham Way	TBA		N	Fibre cement wall and ceiling linings	Rear of Cottage	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPTERT 02892AA	2		Sep-20
Thomson Bay North	12 Bovell Way	TBNO-12BOW	Staff Cottage	N	Profiled fibre cement fence	West, east and south boundaries	2	1	1	3	1	8	A3	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay North	12 Bovell Way	TBNO-12BOW	Staff Cottage	N	Molded fibre cement capping	East boundary	2	1	1	1	1	6	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay North	12 Bovell Way	TBNO-12BOW	Staff Cottage	N	Profiled fibre cement external wall cladding	Perimeter of cottage	1	1	1	0	0	3	A5	17/11/2017	Coffey Environments- Geri Treolar	ENAUPTERT 02892AA	2		Sep-20
Thomson Bay North	12 Bovell Way	TBNO-12BOW	Staff Cottage	N	Corrugated fibre cement fence	North boundary	1	1	1	1	1	5	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay North	14 Boreham Way	TBNO-14BRW	Female Lodge Staff Cottage	N	Profiled fibre cement fence	North and east boundaries	3	1	1	1	1	7	A3	20/09/2017	Coffey Environments	ENAUPTERT 02892AA	2		Sep-20
Thomson Bay North	14 Boreham Way	TBNO-14BRW	Female Lodge Staff Cottage	N	Profiled fibre cement external wall cladding	Perimeter of cottage and outbuildings	3	1	1	2	0	7	A3	20/09/2017	Coffey Environments	ENAUPTERT 02892AA	2		Sep-20
Thomson Bay North	14 Boreham Way	TBNO-14BRW	Female Lodge Staff Cottage	N	Fibre cement wall and ceiling lining	Throughout	2	1	1	0	0	4	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay North	14 Boreham Way	TBNO-14BRW	Female Lodge Staff Cottage	N	Corrugated fibre cement fence	West boundary	1	1	1	1	1	5	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay North	2 Mapleson Road	TBNO-2MPRD	Old police station	N	Corrugated fibre cement fence	Surrounding boundary	2	1	1	2	1	7	A3	18/05/2018	Eurofins: 599071-AID	599071-AID	1	N	May-21
Thomson Bay North	2 Welch Road	TBSO-2WCRO	Staff Cottage	N	Profiled fibre cement external wall cladding	Perimeter of cottage	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPTERT 02892AA	2		Sep-20
Thomson Bay North	2 Welch Road	TBSO-2WCRO	Staff Cottage	N	Fibre cement wall and ceiling linings	Throughout	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay North	2 Welch Road	TBSO-2WCRO	Staff Cottage	N	Fibre cement eaves lining	Perimeter of cottage	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay North	345 Sommerville Drive	TBNO-UN345	Unit 345	N	Corrugated fibre cement fence	Separating Units 345 & 346	2	1	1	3	1	8	A3	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay North	345 Sommerville Drive	TBNO-UN345	Unit 345	N	Fibre cement external wall cladding	Perimeter of Unit	1	1	1	0	0	3	A5	25/11/2017	Coffey Environments- Geri Treolar	ENAUPTERT 02892AA	2		Nov-20
Thomson Bay North	345 Sommerville Drive	TBNO-UN345	Unit 345	N	Fibre cement wall and ceiling linings	Enclosed rear verandah, bathroom & rear bedroom	1	1	1	1	0	4	A5	25/11/2017	Coffey Environments- Geri Treolar	ENAUPTERT 02892AA	2		Nov-20
Thomson Bay North	345 Sommerville Drive	TBNO-UN345	Unit 345	N	Laminated fibre cement walls	Bathroom	1	1	1	0	0	3	A5	25/11/2017	Coffey Environments- Geri Treolar	ENAUPTERT 02892AA	2		Nov-20
Thomson Bay North	346 Sommerville Drive	TBNO-UN346	Unit 346	N	Surface dust	From air extractor vent ducting	1	2	3	3	1	10	A2	25/05/2017	Parry	Apollo 5589	3		Sep-18
Thomson Bay North	346 Sommerville Drive	TBNO-UN346	Unit 346	N	Corrugated fibre cement fence	Separating Units 345 & 346	2	1	1	3	1	8	A3	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay North	346 Sommerville Drive	TBNO-UN346	Unit 346	N	Fibre cement external wall cladding	Perimeter of Unit	1	1	1	0	0	3	A5	25/11/2017	Coffey Environments- Geri Treolar	ENAUPTERT 02892AA	2		Nov-20

GROUP (AREA/ SUBURB)	ADDRESS 1	SITE ID (Maximo Ref)	KNOWN AS	Site Ref	SAMPLE DESCRIPTION	SAMPLE LOCATION	Coffey Environments Risk Assessment							Asbestos Management					
							Asbestos Fibre Type	Surface Treatment	Product Type	Condition	Likelihood of Disturbance	Risk Score	Action Rating	Inspection Date	Asbestos Consultant	Report Reference Number	Inspection Type	Labelled Y/N	Re-inspection Due (as required by [NOHSC:2018 (2005)])
Thomson Bay North	346 Sommerville Drive	TBNO-UN346	Unit 346	N	Fibre cement wall and ceiling linings	Enclosed rear verandah, bathroom & rear bedroom	1	1	1	0	0	3	A5	25/11/2017	Coffey Environments-Geri Treolar	ENAUPT02892AA	2		Nov-20
Thomson Bay North	346 Sommerville Drive	TBNO-UN346	Unit 346	N	Laminated fibre cement walls	Bathroom	1	1	1	0	0	3	A5	25/11/2017	Coffey Environments-Geri Treolar	ENAUPT02892AA	2		Nov-20
Thomson Bay North	4 Welch Road	TBSO-4WCRO	Staff Cottage	N	Fibre cement external wall cladding	Perimeter of Cottage	1	1	1	1	0	4	A4	17/10/2017	Coffey Environments	ENAUPT02892AA	2		Oct-18
Thomson Bay North	4 Welch Road	TBSO-4WCRO	Staff Cottage	N	Laminated fibre cement wall linings	Kitchen and Bathroom	1	1	1	1	0	4	A4	17/10/2017	Coffey Environments	ENAUPT02892AA	2		Oct-18
Thomson Bay North	4 Welch Road	TBSO-4WCRO	Staff Cottage	N	Vinyl floor tiles	Laundry	1	0	1	0	0	2	A5	17/10/2017	Coffey Environments	ENAUPT02892AA	2		Oct-18
Thomson Bay North	4 Welch Road	TBSO-4WCRO	Staff Cottage	N	Fibre cement wall and ceiling linings	Laundry, Bathroom and Toilet	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPT02892AA	2		Oct-18
Thomson Bay North	401 Abbott Street	TBNO-UN401	Unit 401	N	Fibre cement external wall cladding	Perimeter of Unit	3	1	1	2	0	7	A3	20/09/2017	Coffey Environments	ENAUPT02892AA	2		Sep-20
Thomson Bay North	401 Abbott Street	TBNO-UN401	Unit 401	N	Molded fibre cement external wall capping	Perimeter of Unit	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPT02892AA	2		Nov-20
Thomson Bay North	402 Abbott Street	TBNO-UN402	Units 402	N	Fibre cement external wall cladding	Perimeter of Unit	3	1	1	2	0	7	A3	20/09/2017	Coffey Environments	ENAUPT02892AA	2		Sep-20
Thomson Bay North	402 Abbott Street	TBNO-UN402	Units 402	N	Molded fibre cement external wall capping	Perimeter of Unit	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPT02892AA	2		Nov-20
Thomson Bay North	404 Abbott Street	TBNO-UN404	Unit 404	N	Fibre cement external wall cladding	Perimeter of Unit	3	1	1	1	1	7	A3	20/09/2017	Coffey Environments	ENAUPT02892AA	2		Sep-20
Thomson Bay North	404 Abbott Street	TBNO-UN404	Unit 404	N	Molded fibre cement external wall capping	Perimeter of Unit	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPT02892AA	2		Nov-20
Thomson Bay North	411 Abbott Street	TBNO-UN411	Units 411	N	Fibre cement external wall cladding	Perimeter of Unit	3	1	1	1	1	7	A3	20/09/2017	Coffey Environments	ENAUPT02892AA	2		Sep-20
Thomson Bay North	411 Abbott Street	TBNO-UN411	Units 411	N	Molded fibre cement external wall capping	Perimeter of Unit	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPT02892AA	2		Nov-20
Thomson Bay North	414 Kelly Street	TBNO-UN414	Unit 414	N	Fibre cement external wall cladding	Perimeter of Unit	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPT02892AA	2		Sep-20
Thomson Bay North	414 Kelly Street	TBNO-UN414	Unit 414	N	Fibre cement wall lining	Enclosed rear verandah	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPT02892AA	2		Sep-20
Thomson Bay North	414 Kelly Street	TBNO-UN414	Unit 414	N	Fibre cement lower half of walls	Kitchen	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPT02892AA	2		Sep-20
Thomson Bay North	414 Kelly Street	TBNO-UN414	Unit 414	N	Fibre cement ceiling lining	Enclosed rear verandah	2	1	1	0	0	4	A4	17/10/2017	Coffey Environments	ENAUPT02892AA	2		Oct-18
Thomson Bay North	414 Kelly Street	TBNO-UN414	Unit 414	N	Fibre cement wall and ceiling lining	Enclosed front verandah	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPT02892AA	2		Nov-20
Thomson Bay North	414 Kelly Street	TBNO-UN414	Unit 414	N	Beige vinyl floor tiles	Throughout Unit	1	0	1	0	0	2	A5	17/10/2017	Coffey Environments	ENAUPT02892AA	2		Oct-18
Thomson Bay North	415 Kelly Street	TBNO-UN415	Unit 415	N	Fibre cement external wall cladding	Perimeter of Unit	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPT02892AA	2		Sep-20
Thomson Bay North	415 Kelly Street	TBNO-UN415	Unit 415	N	Molded fibre cement external wall capping	Perimeter of Unit	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPT02892AA	2		Nov-20
Thomson Bay North	417 Kelly Street	TBNO-UN417	Unit 417	N	Fibre cement external wall cladding	Perimeter of Unit	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPT02892AA	2		Sep-20
Thomson Bay North	417 Kelly Street	TBNO-UN417	Unit 417	N	Fibre cement external wall cladding	Perimeter of Unit	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPT02892AA	2		Sep-20
Thomson Bay North	418 Kelly Street	TBNO-UN418	Unit 418	N	Fibre cement external wall cladding	Perimeter of Unit	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPT02892AA	2		Sep-20
Thomson Bay North	420 Kelly Street	TBNO-UN420	Unit 420	N	Fibre cement external wall cladding	Perimeter of Unit	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPT02892AA	2		Sep-20
Thomson Bay North	421 Kelly Street	TBNO-UN421	Unit 421	N	Fibre cement external wall cladding	Perimeter of Unit	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPT02892AA	2		Sep-20
Thomson Bay North	442 Boreham Way	TBNO-UN442	Cottage 442	N	Profiled fibre cement fence	Property boundary between 442 and 443	3	1	1	1	1	7	A3	20/09/2017	Coffey Environments	ENAUPT02892AA	2		Sep-20
Thomson Bay North	442 Boreham Way	TBNO-UN442	Cottage 442	N	Fibre cement eaves and verandah ceiling linings	Perimeter of cottage	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPT02892AA	2		Oct-18
Thomson Bay North	442 Boreham Way	TBNO-UN442	Cottage 442	N	Fibre cement ceiling and wall lining	Laundry and Bathroom	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPT02892AA	2		Oct-18
Thomson Bay North	442 Boreham Way	TBNO-UN442	Cottage 442	N	Fibre cement external wall cladding	Perimeter of cottage	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPT02892AA	2		Oct-18
Thomson Bay North	443 Boreham Way	TBNO-UN443	Cottage 443	N	Profiled fibre cement fence	Property boundary between 442 and 443	3	1	1	1	1	7	A3	20/09/2017	Coffey Environments	ENAUPT02892AA	2		Sep-20
Thomson Bay North	443 Boreham Way	TBNO-UN443	Cottage 443	N	Profiled fibre cement external wall cladding	Perimeter of cottage	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPT02892AA	2		Sep-20
Thomson Bay North	443 Boreham Way	TBNO-UN443	Cottage 443	N	Fibre cement ceiling and wall lining	Throughout	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPT02892AA	2		Oct-18
Thomson Bay North	444 Boreham Way	TBNO-UN444	Cottage 444	N	Profiled fibre cement external wall cladding	Perimeter of cottage	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPT02892AA	2		Sep-20
Thomson Bay North	444 Boreham Way	TBNO-UN444	Cottage 444	N	Fibre cement ceiling and wall lining	Throughout	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPT02892AA	2		Oct-18
Thomson Bay North	8 Bovell Way	TBNO-451BW	Golf Club Cottage	N	Fibre cement external wall cladding	Perimeter of cottage	3	1	1	2	0	7	A3	20/09/2017	Coffey Environments	ENAUPT02892AA	2		Sep-20
Thomson Bay North	8 Bovell Way	TBNO-451BW	Golf Club Cottage	N	Fibre cement wall and ceiling linings	Laundry, Shower and Toilet	3	1	1	0	0	5	A4	25/11/2017	Coffey Environments-Geri Treolar	ENAUPT02892AA	2		Nov-20
Thomson Bay North	8 Bovell Way	TBNO-451BW	Golf Club Cottage	N	Molded cement vent pipe	Rear of Property	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPT04220AA	1		Oct-18
Thomson Bay North	8 Kelly Street	TBNO-451BW	Public Shower Block	N	Dust fibres in ceiling	Entryway	1	3	3	1	1	9	A4	18/05/2018	Eurofins: 598653-AID	Eurofins	2		May-21
Thomson Bay North	8 Kitson Street	Demolished	Staff Cottage	N	Profiled fibre cement fence	Rear boundary	3	1	1	1	1	7	A3	20/09/2017	Coffey Environments	ENAUPT02892AA	2		Sep-20
Thomson Bay North	8 Kitson Street	Demolished	Staff Cottage	N	Fibre cement external wall cladding	Perimeter of Cottage	2	1	1	0	0	4	A4	17/09/2017	Coffey Environments	ENAUPT02892AA	2		Sep-20

GROUP (AREA/ SUBURB)	ADDRESS 1	SITE ID (Maximo Ref)	KNOWN AS	Site Ref	SAMPLE DESCRIPTION	SAMPLE LOCATION	Coffey Environments Risk Assessment							Asbestos Management					
							Asbestos Fibre Type	Surface Treatment	Product Type	Condition	Likelihood of Disturbance	Risk Score	Action Rating	Inspection Date	Asbestos Consultant	Report Reference Number	Inspection Type	Labelled Y/N	Re-inspection Due (as required by [NOHSC:2018 (2005)])
Thomson Bay North	8 Kitson Street	Demolished	Staff Cottage	N	Fibre cement wall lining	Throughout	2	1	1	0	0	4	A4	17/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay North	8 Kitson Street	Demolished	Staff Cottage	N	Corrugated fibre cement fence	Rear boundary	2	1	1	1	1	6	A4	17/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	1 Bedford Avenue	KING-HTRNS	Rottnest Hotel	N	Fibre cement external wall cladding and gables	Old Staff Accommodation block	1	1	1	0	0	3	A4	25/11/2017	Coffey Environments Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Thomson Bay South	1 Brand Highway	TBNO-GOCSE	Garden Golf Kiosk	N	Molded fibre cement roof and wall cladding	Kiosk	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Thomson Bay South	1 Workshop Road South	TBSO-1PFMY	Workshop Cottage No.1	N	Fibre cement external wall cladding	Perimeter of Cottage	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Thomson Bay South	1 Workshop Road South	TBSO-1PFMY	Workshop Cottage No.1	N	Fibre cement ceiling and wall linings	Throughout cottage	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Thomson Bay South	10 Bedford Avenue	TBSO-10BAV	Staff Cottage	N	Fibre cement external wall cladding	Perimeter of Cottage	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPERT 02892AA	2		Oct-18
Thomson Bay South	10 Bedford Avenue	TBSO-10BAV	Staff Cottage	N	Fibre cement wall and ceiling linings	Front sleep out	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPERT 02892AA	2		Oct-18
Thomson Bay South	10 Bedford Avenue	TBSO-10BAV	Staff Cottage	N	Corrugated fibre cement fence	Property boundaries	2	1	1	1	1	6	A4	17/10/2017	Coffey Environments	ENAUPERT 02892AA	2		Oct-18
Thomson Bay South	10 Workshop Road	TBSO-PFMOP	PFM Workshop	N	Molded fibre cement cable pits	Perimeter of building	2	1	1	2	1	7	A3	25/11/2017	Coffey Environments Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Thomson Bay South	10 Workshop Road	TBSO-PFMOP	PFM Workshop	N	Fibre cement capping	Roof and walls	2	1	1	1	0	5	A4	25/11/2017	Coffey Environments Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Thomson Bay South	10 Workshop Road	TBSO-PFMOP	PFM Workshop	N	Molded fibre cement gutters and downpipes	To building	2	1	1	1	0	5	A4	25/11/2017	Coffey Environments Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Thomson Bay South	10 Workshop Road	TBSO-PFMOP	PFM Workshop	N	Corrugated fibre cement sheeting	Roof of building	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Thomson Bay South	10 Workshop Road	TBSO-PFMOP	PFM Workshop	N	Corrugated fibre cement external wall cladding	Perimeter of building	2	1	1	2	0	6	A4	25/11/2017	Coffey Environments Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Thomson Bay South	10 Workshop Road	TBSO-PFMOP	PFM Workshop	N	Fibre cement ceiling and wall linings	Offices of Carentry/Painters &	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Thomson Bay South	12 Bedford Avenue	TBSO-12BAV	Staff Cottage	N	Fibre cement external wall cladding	Perimeter of Cottage	1	1	1	2	0	5	A4	17/10/2017	Coffey Environments	ENAUPERT 02892AA	2		Oct-18
Thomson Bay South	12 Bedford Avenue	TBSO-12BAV	Staff Cottage	N	Fibre cement wall and ceiling linings	Front sleep out	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPERT 02892AA	2		Oct-18
Thomson Bay South	12 Bedford Avenue	TBSO-12BAV	Staff Cottage	N	Fibre cement wall and ceiling linings	Toilet and Laundry	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPERT 02892AA	2		Oct-18
Thomson Bay South	12 Bedford Avenue	TBSO-12BAV	Staff Cottage	N	Fibre cement east wall lining	Bathroom	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPERT 02892AA	2		Oct-18
Thomson Bay South	12 Bedford Avenue	TBSO-12BAV	Staff Cottage	N	Corrugated fibre cement fence	North boundary	2	1	1	1	1	6	A4	17/10/2017	Coffey Environments	ENAUPERT 02892AA	2		Oct-18
Thomson Bay South	12 Brand Way	TBSO-12BWA	Staff Cottage	N	Corrugated fibre cement fence	Property Boundaries	2	1	1	2	1	7	A3	17/08/2017	Eurofins: 559005-AID	J.Wright	2		Aug-20
Thomson Bay South	12 Brand Way	TBSO-12BWA	Staff Cottage	N	Fibre cement external wall cladding	Bird cage	1	1	1	1	1	5	A4	17/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	12 Brand Way	TBSO-12BWA	Staff Cottage	N	Fibre cement external wall cladding	Perimeter of Cottage	1	1	1	0	0	3	A5	17/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	12 Brand Way	TBSO-12BWA	Staff Cottage	N	Fibre cement wall and ceiling linings	Enclosed rear verandah	1	1	1	0	0	3	A5	17/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	12 Brand Way	TBSO-12BWA	Staff Cottage	N	Laminated fibre cement splash back wall lining	Laundry	1	1	1	0	0	3	A5	17/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	13 Bedford Avenue	TBSO-13BFD	Staff Cottage	N	Fibre cement vent pipe	Laundry	2	1	1	0	0	4	A4	17/10/2017	Coffey Environments	ENAUPERT 02892AA	2		Oct-18
Thomson Bay South	13 Bedford Avenue	TBSO-13BFD	Staff Cottage	N	Fibre cement external wall cladding	Perimeter of Cottage	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPERT 02892AA	2		Oct-18
Thomson Bay South	13 Bedford Avenue	TBSO-13BFD	Staff Cottage	N	Fibre cement low wall linings	Kitchen and Bathroom	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPERT 02892AA	2		Oct-18
Thomson Bay South	13 Bedford Avenue	TBSO-13BFD	Staff Cottage	N	Fibre cement ceiling lining	Outside Laundry	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPERT 02892AA	2		Oct-18
Thomson Bay South	13 Bedford Avenue	TBSO-13BFD	Staff Cottage	N	Corrugated fibre cement fence	Property Boundaries	2	1	1	1	1	6	A4	17/10/2017	Coffey Environments	ENAUPERT 02892AA	2		Oct-18
Thomson Bay South	13 Brand Highway	TBSO-13BWY	Staff Cottage	N	Corrugated fibre cement fence	Front boundary	2	1	1	2	1	7	A3	17/10/2017	Coffey Environments	ENAUPERT 02892AA	2		Oct-18
Thomson Bay South	13 Brand Highway	TBSO-13BWY	Staff Cottage	N	Fibre cement external wall cladding	Perimeter of Cottage	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	13 Brand Highway	TBSO-13BWY	Staff Cottage	N	cement pipe set into ground in front of property	External	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	1		Sep-20
Thomson Bay South	2 Workshop Road South	TBSO-2PFMY	Workshop Cottage No.2	N	Fibre cement external wall cladding	Rear enclosed verandahs	1	1	1	0	1	8	A3	25/11/2017	Coffey Environments Geri Treolar	ENAUPERT 02892AA	2		Oct-18
Thomson Bay South	2 Workshop Road South	TBSO-2PFMY	Workshop Cottage No.2	N	Profiled fibre cement fence	Rear boundary	2	1	1	1	1	6	A4	25/11/2017	Coffey Environments Geri Treolar	ENAUPERT 02892AA	2		Nov-20
Thomson Bay South	201 Vlamingh Way	TBSO-UN201	Unit 201	N	Fibre cement eaves and verandah lining	Front & rear of building	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	201 Vlamingh Way	TBSO-UN201	Unit 201	N	Fibre cement ceiling lining	Throughout building	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	203 Vlamingh Way	TBSO-UN203	Unit 203	N	Fibre cement eaves and verandah lining	Front & rear of building	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	203 Vlamingh Way	TBSO-UN203	Unit 203	N	Fibre cement ceiling lining	Throughout building	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	207 Vlamingh Way	TBSO-UN207	Unit 207	N	Fibre cement eaves and verandah lining	Front & rear of building	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	207 Vlamingh Way	TBSO-UN207	Unit 207	N	Fibre cement ceiling lining	Throughout building	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	212 Vlamingh Way	TBSO-UN212	Unit 212	N	Fibre cement eaves and verandah lining	Front & rear of building	3	1	1	1	0	6	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20

GROUP (AREA/ SUBURB)	ADDRESS 1	SITE ID (Maximo Ref)	KNOWN AS	Site Ref	SAMPLE DESCRIPTION	SAMPLE LOCATION	Coffey Environments Risk Assessment							Asbestos Management					
							Asbestos Fibre Type	Surface Treatment	Product Type	Condition	Likelihood of Disturbance	Risk Score	Action Rating	Inspection Date	Asbestos Consultant	Report Reference Number	Inspection Type	Labelled Y/N	Re-inspection Due (as required by [NOHSC:2018 (2005)])
Thomson Bay South	212 Vlamingh Way	TBSO-UN212	Unit 212	N	Fibre cement ceiling lining	Throughout building	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	214 Vlamingh Way	TBSO-UN214	Unit 214	N	Fibre cement eaves and verandah lining	Front & rear of building	3	1	1	1	0	6	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	214 Vlamingh Way	TBSO-UN214	Unit 214	N	Fibre cement ceiling lining	Throughout building	3	1	1	1	0	6	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	216 Vlamingh Way	TBSO-UN216	Unit 216	N	Fibre cement eaves and verandah lining	Front & rear of building	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	216 Vlamingh Way	TBSO-UN216	Unit 216	N	Fibre cement ceiling lining	Throughout building	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	218 Vlamingh Way	TBSO-UN218	Unit 218	N	Fibre cement eaves and verandah lining	Front & rear of building	3	1	1	1	0	6	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	218 Vlamingh Way	TBSO-UN218	Unit 218	N	Fibre cement ceiling lining	Throughout building	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	221 Vlamingh Way	TBSO-UN221	Unit 221	N	Fibre cement eaves and verandah lining	Perimeter of building	3	1	1	1	0	6	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	224 Vlamingh Way	TBSO-UN224	Unit 224	N	Fibre cement eaves and verandah lining	Perimeter of building	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	224 Vlamingh Way	TBSO-UN224	Unit 224	N	Fibre cement ceiling linings	Throughout	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	225 Vlamingh Way	TBSO-UN225	Unit 225	N	Fibre cement ceiling lining	Bathroom	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	226 Vlamingh Way	TBSO-UN226	Unit 226	N	Fibre cement ceiling lining	Bathroom	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	227 Vlamingh Way	TBSO-UN227	Unit 227	N	Fibre cement eaves and verandah lining	Perimeter of building	3	1	1	1	0	6	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	227 Vlamingh Way	TBSO-UN227	Unit 227	N	Fibre cement ceiling lining	Throughout	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	229 Vlamingh Way	TBSO-UN229	Unit 229	N	Fibre cement ceiling linings	Throughout	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	23 Parker Point Road	TBAY-23PPR	Staff Cottage	N	Corrugated fibre cement fence	Property boundary	2	1	1	2	1	7	A3	17/10/2017	Coffey Environments	ENAUPERT 02892AA	2		Oct-18
Thomson Bay South	23 Parker Point Road	TBAY-23PPR	Staff Cottage	N	Profiled fibre cement external wall cladding	Perimeter of cottage	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	23 Parker Point Road	TBAY-23PPR	Staff Cottage	N	Fibre cement ceiling lining	Front Porch	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPERT 02892AA	2		Oct-18
Thomson Bay South	23 Parker Point Road	TBAY-23PPR	Staff Cottage	N	Fibre cement wall and ceiling linings	Throughout cottage	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPERT 02892AA	2		Oct-18
Thomson Bay South	230 Vlamingh Way	TBSO-UN230	Unit 230	N	Fibre cement ceiling linings	Throughout	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	233 Vlamingh Way	TBSO-UN233	Unit 233	N	Fibre cement eaves and verandah lining	Perimeter of building	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	233 Vlamingh Way	TBSO-UN233	Unit 233	N	Fibre cement ceiling lining	Throughout	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	234 Vlamingh Way	TBSO-UN234	Unit 234	N	Fibre cement ceiling lining	Throughout	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	237 Vlamingh Way	TBSO-UN237	Unit 237	N	Fibre cement ceiling lining	Throughout	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	239 Vlamingh Way	TBSO-UN239	Unit 239	N	Fibre cement eaves and verandah lining	Perimeter of building	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	239 Vlamingh Way	TBSO-UN239	Unit 239	N	Fibre cement ceiling linings	Throughout	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	240 Vlamingh Way	TBSO-UN240	Unit 240	N	Fibre cement ceiling linings	Throughout	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	246 Vlamingh Way	TBSO-UN246	Unit 246	N	Fibre cement eaves and verandah lining	Perimeter of building	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	246 Vlamingh Way	TBSO-UN246	Unit 246	N	Fibre cement ceiling lining	Throughout	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	25 Parker Point Road	TBSO-25PPR	Staff Cottage	N	Corrugated fibre cement fence	Property boundary	2	1	1	3	1	8	A3	17/10/2017	Coffey Environments	ENAUPERT 02892AA	2		Oct-18
Thomson Bay South	25 Parker Point Road	TBSO-25PPR	Staff Cottage	N	Profiled fibre cement external wall cladding	Perimeter of cottage	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	25 Parker Point Road	TBSO-25PPR	Staff Cottage	N	Fibre cement ceiling lining	Front Porch	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPERT 02892AA	2		Oct-18
Thomson Bay South	25 Parker Point Road	TBSO-25PPR	Staff Cottage	N	Fibre cement wall and ceiling linings	Throughout cottage	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPERT 02892AA	2		Oct-18
Thomson Bay South	26 Parker Point Road	TBSO-26PPR	Staff Cottage	N	Corrugated fibre cement fence	Property boundary	2	1	1	2	1	7	A3	17/10/2017	Coffey Environments	ENAUPERT 02892AA	2		Oct-18
Thomson Bay South	26 Parker Point Road	TBSO-26PPR	Staff Cottage	N	Profiled fibre cement external wall cladding	Perimeter of cottage	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	26 Parker Point Road	TBSO-26PPR	Staff Cottage	N	Fibre cement ceiling lining	Front Porch	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPERT 02892AA	2		Oct-18
Thomson Bay South	26 Parker Point Road	TBSO-26PPR	Staff Cottage	N	Fibre cement wall and ceiling linings	Throughout cottage	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPERT 02892AA	2		Oct-18
Thomson Bay South	27 Parker Point Road	TBSO-27PPR	Staff Cottage	N	Profiled fibre cement external wall cladding	Perimeter of cottage	3	1	1	2	0	7	A3	7/10/2017	Apollo Inspectorate	AIP17109.004	2		Oct-20
Thomson Bay South	27 Parker Point Road	TBSO-27PPR	Staff Cottage	N	Corrugated fibre cement fence	Property boundary	2	1	1	1	1	6	A4	7/10/2017	Apollo Inspectorate	AIP17109.004	2		Oct-20
Thomson Bay South	28 Parker Point Road	TBSO-28PPR	Staff Cottage	N	Corrugated fibre cement fence	Property boundary	2	1	1	2	1	7	A3	17/10/2017	Coffey Environments	ENAUPERT 02892AA	2		Oct-18
Thomson Bay South	28 Parker Point Road	TBSO-28PPR	Staff Cottage	N	Profiled fibre cement external wall cladding	Perimeter of cottage	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPERT 02892AA	2		Sep-20
Thomson Bay South	28 Parker Point Road	TBSO-28PPR	Staff Cottage	N	Fibre cement ceiling lining	Front Porch	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPERT 02892AA	2		Oct-18



GROUP (AREA/ SUBURB)	ADDRESS 1	SITE ID (Maximo Ref)	KNOWN AS	Site Ref	SAMPLE DESCRIPTION	SAMPLE LOCATION	Coffey Environments Risk Assessment							Asbestos Management					
							Asbestos Fibre Type	Surface Treatment	Product Type	Condition	Likelihood of Disturbance	Risk Score	Action Rating	Inspection Date	Asbestos Consultant	Report Reference Number	Inspection Type	Labelled Y/N	Re-inspection Due (as required by [NOHSC:2018 (2005)])
Thomson Bay South	28 Parker Point Road	TBSO-28PPR	Staff Cottage	N	Fibre cement wall and ceiling linings	Throughout cottage	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay South	29 Parker Point Road	TBSO-29PPR	Staff Cottage	N	Corrugated fibre cement fence	Property boundary	2	1	1	3	1	8	A3	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay South	29 Parker Point Road	TBSO-29PPR	Staff Cottage	N	Profilled fibre cement external wall cladding	Perimeter of cottage	3	1	1	1	0	6	A4	20/09/2017	Coffey Environments	ENAUPTERT 02892AA	2		Sep-20
Thomson Bay South	29 Parker Point Road	TBSO-29PPR	Staff Cottage	N	Fibre cement ceiling lining	Front Porch	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay South	29 Parker Point Road	TBSO-29PPR	Staff Cottage	N	Fibre cement wall and ceiling linings	Throughout cottage	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay South	3 Henderson Avenue	TBSO-RIAEO	Rottnest Island Authority Office	N	Molded fibre cement cable pits	North west corner	3	1	1	1	1	7	A3	20/09/2017	Coffey Environments	ENAUPTERT 02892AA	2		Sep-20
Thomson Bay South	3 Parker Point Road	TBSO-3PPRD	Staff Cottage	N	Profilled fibre cement external wall cladding	Perimeter of cottage	3	1	1	1	0	6	A4	20/09/2017	Coffey Environments	ENAUPTERT 02892AA	2		Sep-20
Thomson Bay South	3 Parker Point Road	TBSO-3PPRD	Staff Cottage	N	Fibre cement eaves and front porch ceiling lining	Perimeter of cottage	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay South	3 Workshop Road South	TBSO-3PFMY	Workshop Cottage No.3 (Structural)	N	Fibre cement external wall cladding	Front enclosed verandah	2	1	1	2	0	6	A4	25/11/2017	Coffey Environments- Geri Treolar	ENAUPTERT 02892AA	2		Nov-20
Thomson Bay South	31 Parker Point Road	TBSO-31PPR	Staff Cottage	N	Corrugated fibre cement fence	Property boundary	2	1	1	2	1	7	A3	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay South	31 Parker Point Road	TBSO-31PPR	Staff Cottage	N	Profilled fibre cement external wall cladding	Perimeter of cottage	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPTERT 02892AA	2		Sep-20
Thomson Bay South	31 Parker Point Road	TBSO-31PPR	Staff Cottage	N	Fibre cement ceiling lining	Front Porch	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay South	31 Parker Point Road	TBSO-31PPR	Staff Cottage	N	Fibre cement wall and ceiling linings	Throughout cottage	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay South	4 Parker Point Road	TBSO-04PPR	Staff Cottage	N	Fibre cement external wall cladding	Perimeter of cottage and out building	2	1	1	0	0	4	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay South	4 Parker Point Road	TBSO-04PPR	Staff Cottage	N	Fibre cement wall and ceiling lining	Rear verandah internal	2	1	1	0	0	4	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay South	4 Parker Point Road	TBSO-04PPR	Staff Cottage	N	Fibre cement north wall lining	laundry	2	1	1	0	0	4	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay South	4 Parker Point Road	TBSO-04PPR	Staff Cottage	N	Small corrugated fibre cement external wall cladding	Out building	1	1	1	1	1	5	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay South	4 Parker Point Road	TBSO-04PPR	Staff Cottage	N	Small corrugated fibre cement fence	South boundary	1	1	1	1	1	5	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay South	4 Parker Point Road	TBSO-04PPR	Staff Cottage	N	Corrugated fibre cement low fence	Front boundary	2	1	1	1	1	6	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay South	5 Brand Highway	TBSO-PWHOU	Power House	N	Woven rope lagging to exhaust	To Generator No.4 (old)	1	1	2	1	1	6	A4	25/11/2017	Coffey Environments- Geri Treolar	ENAUPTERT 02892AA	2		Nov-20
Thomson Bay South	5 Brand Highway	TBSO-PWHOU	Power House	N	Gasket to exhaust	To Generator No.6	1	0	1	1	1	4	A4	25/11/2017	Coffey Environments- Geri Treolar	ENAUPTERT 04220AA	2		Nov-20
Thomson Bay South	5 Brand Highway	TBSO-PWHOU	Power House	N	Fibre cement ceiling and wall lining	In Offices	2	1	1	2	0	6	A4	25/11/2017	Coffey Environments- Geri Treolar	ENAUPTERT 02892AA	2		Nov-20
Thomson Bay South	5 Brand Highway	TBSO-PWHOU	Power House	N	Fibre cement ceiling and wall linings	South end of Lunch Room, Toilets and external wall of	2	1	1	0	0	4	A4	25/11/2017	Coffey Environments- Geri Treolar	ENAUPTERT 02892AA	2		Nov-20
Thomson Bay South	5 Brand Highway	TBSO-PWHOU	Power House	N	Fibre cement debris	Open ground to south of resistors at powerhouse	1	1	1	3	1	7	A3	20/09/2017	PR-PFM	PFM	1		Apr-19
Thomson Bay South	6 Brand Highway	TBSO-06BWY	Staff Cottage	N	Profilled fibre cement external wall cladding	Perimeter of Cottage	3	1	1	3	0	8	A3	20/09/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay South	6 Parker Point Road	TBSO-6PPRD	Staff Cottage	N	Fibre cement external wall cladding	Perimeter of cottage	2	1	1	0	0	4	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay South	6 Parker Point Road	TBSO-6PPRD	Staff Cottage	N	Fibre cement wall and ceiling lining	Enclosed front and rear verandahs	2	1	1	0	0	4	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay South	6 Parker Point Road	TBSO-6PPRD	Staff Cottage	N	Corrugated fibre cement low fence	Front boundary	2	1	1	1	1	6	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay South	6 Parker Point Road	TBSO-6PPRD	Staff Cottage	N	Corrugated fibre cement fence	Sides and rear boundaries	2	1	1	1	1	6	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay South	7 Brand Highway	TBSO-07BWY	Staff Cottage	N	Corrugated fibre cement fence	Property boundary	2	1	1	2	1	7	A3	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay South	7 Brand Highway	TBSO-07BWY	Staff Cottage	N	Fibre cement external wall cladding	Rear of cottage	3	1	2	1	2	9	A4	20/09/2017	Apollo Inspectorate	AIP18009.008	2		Feb-19
Thomson Bay South	7 Brand Highway	TBSO-07BWY	Staff Cottage	N	Vinyl floor tiles beneath modern	Kitchen Floor	1	1	1	1	1	5	A4	13/02/2018	Apollo Inspectorate	584594-AID			Feb-21
Thomson Bay South	7 Brand Highway	TBSO-07BWY	Staff Cottage	N	Fibre cement debris - Ceiling void 80m <sup>2</sup>	Ceiling void	1	2	3	3	1	10	A2	14/02/2018	Apollo Inspectorate	AIP18009.008	2		Feb-19
Thomson Bay South	7 Brand Highway	TBSO-07BWY	Staff Cottage	N	Vinyl floor tiles beneath modern	Toilet Floor	1	1	0	1	1	4	A3	14/02/2018	Apollo Inspectorate	AIP18009.008	2		Feb-19
Thomson Bay South	7 Brand Highway	TBSO-07BWY	Staff Cottage	N	Rear of House around doorway 6m <sup>2</sup>	Rear external doorway	3	1	2	1	2	9	A4	14/02/2018	Apollo Inspectorate	AIP18009.008	2		Feb-19
Thomson Bay South	7 Brand Highway	TBSO-07BWY	Staff Cottage	N	Fibre cement sheet 2m <sup>2</sup>	Front verandah gable ends	3	1	2	1	1	8	A3	14/02/2018	Apollo Inspectorate	AIP18009.008	2		Feb-19
Thomson Bay South	7 Brand Highway	TBSO-07BWY	Staff Cottage	N	Molded fibre cement fence capping	Property boundary	2	1	1	1	1	6	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay South	7 Parker Point Road	TBSO-7PPRD	Staff Cottage	N	Fibre cement external wall cladding	Perimeter of cottage	2	1	1	0	0	4	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay South	8 Brand Highway	TBSO-8BRDW	Staff Cottage	N	Profilled fibre cement external wall cladding	Perimeter of Cottage	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPTERT 02892AA	2		Sep-20
Thomson Bay South	8 Brand Highway	TBSO-8BRDW	Staff Cottage	N	Fibre cement ceiling linings	Porches (x4)	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPTERT 02892AA	1		Sep-20
Thomson Bay South	9 Bedford Avenue	TBSO-9BDFD	Staff Cottage	N	Profilled fibre cement external wall cladding	Perimeter of cottage	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPTERT 02892AA	2		Sep-20

GROUP (AREA/ SUBURB)	ADDRESS 1	SITE ID (Maximo Ref)	KNOWN AS	Site Ref	SAMPLE DESCRIPTION	SAMPLE LOCATION	Coffey Environments Risk Assessment							Asbestos Management					
							Asbestos Fibre Type	Surface Treatment	Product Type	Condition	Likelihood of Disturbance	Risk Score	Action Rating	Inspection Date	Asbestos Consultant	Report Reference Number	Inspection Type	Labelled Y/N	Re-inspection Due (as required by [NOHSC:2018 (2005)])
Thomson Bay South	9 Bedford Avenue	TBSO-9BDFD	Staff Cottage	N	Fibre cement wall and ceiling linings	Throughout	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay South	9 Bedford Avenue	TBSO-9BDFD	Staff Cottage	N	Fibre cement eaves lining	Perimeter of cottage	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay South	9 Bedford Avenue	TBSO-9BDFD	Staff Cottage	N	Laminated fibre cement splash back wall lining	Laundry	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay South	9 Brand Highway	TBSO-9BDWY	Staff Cottage	N	Profiled fibre cement fence	Rear Patio	3	1	1	1	1	7	A3	20/09/2017	Coffey Environments - Geri Treolar	ENAUPTERT 02892AA	2		Sep-20
Thomson Bay South	9 Brand Highway	TBSO-9BDWY	Staff Cottage	N	Corrugated fibre cement fence	Property boundary	2	1	1	1	1	6	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay South	9 Brand Highway	TBSO-9BDWY	Staff Cottage	N	Molded fibre cement fence capping	Property boundary	2	1	1	1	1	6	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay South	9 Parker Point Road	TBSO-9PPRD	Staff Cottage	N	Corrugated fibre cement fence	Property boundary	2	1	1	2	1	7	A3	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	1		Oct-18
Thomson Bay South	9 Parker Point Road	TBSO-9PPRD	Staff Cottage	N	Old asbestos pipe protruding from ground	Next door to 9 Parker Point Road	3	1	1	2	1	8	A3	20/09/2017	Programmed Facility Management	Simon Stuart	1		Oct-18
Thomson Bay South	9 Parker Point Road	TBSO-9PPRD	Staff Cottage	N	Profiled fibre cement external wall cladding	Perimeter of cottage	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments - Geri Treolar	ENAUPTERT 02892AA	2		Sep-20
Thomson Bay South	9 Parker Point Road	TBSO-9PPRD	Staff Cottage	N	Molded fibre cement gutters and downpipes	Front Porch	2	1	1	1	0	5	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay South	9 Parker Point Road	TBSO-9PPRD	Staff Cottage	N	Fibre cement ceiling lining	Front and rear verandahs	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay South	9 Parker Point Road	TBSO-9PPRD	Staff Cottage	N	Fibre cement wall and ceiling linings	Bathroom and Laundry	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay South	Workshop Road North/ Watjil Road	TBSO-HEAHO	Headlam House	N	Fibre cement ceiling and wall linings	Rear enclosed verandah, Toilet and Shower area & Rear enclosed verandah north side	3	1	1	1	1	7	A3	20/09/2017	Coffey Environments	ENAUPTERT 02892AA	2		Sep-20
Thomson Bay South	Workshop Road North/ Watjil Road	TBSO-HEAHO	Headlam House	N	Small corrugated fibre cement external wall cladding	Rear enclosed verandah north side	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPTERT 02892AA	2		Sep-20
Thomson Bay South	Workshop Road North/ Watjil Road	TBSO-TBA	Watjil Place Shed	N	Watjil Place Shed	Shed Walls	1	1	1	3	2	8	A4	14/08/2017	Gordon Waddingham	Eurofin 558676	2		Aug-20
Thomson Bay South	Workshop Road South	TBSO-PFMPR	Storage Sheds (x2)	N	Fibre cement external wall cladding	Perimeter of Sheds (x2)	2	1	1	1	1	6	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay North	12 Bovell Way	TBNO-12BOW	Country Club	N	Fibre cement ceiling lining	1st and ground floor Verandahs & kitchens	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPTERT 02892AA	2		Sep-20
Thomson Bay North	12 Bovell Way	TBNO-12BOW	Country Club	N	Fibre cement infill panels below windows	Front of 1st floor	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPTERT 02892AA	2		Sep-20
Thomson Bay North	12 Bovell Way	TBNO-12BOW	Country Club	N	Fibre cement external wall cladding	1st floor at front of country club	2	1	1	0	0	4	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Thomson Bay North	12 Bovell Way	TBNO-12BOW	Country Club	N	Molded fibre cement pipe	4th Tee	1	1	1	1	1	5	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Wadjemup	Wadjemup Road	TBA	Caretakers Cottage	N	Fibre cement external wall cladding	Top half of building	2	1	1	1	0	5	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Wadjemup	Wadjemup Road	TBA	Caretakers Cottage	N	Fibre cement ceiling and wall lining	Throughout building	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Wadjemup	Wadjemup Road	TBA	Lighthouse Out Buildings	N	Molded fibre cement pipe in ground	Adjacent water tank structure	1	1	1	1	0	4	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Wadjemup	Wadjemup Road	TBA	Lighthouse Out Buildings	N	Fibre cement external wall cladding	Out building adjacent lighthouse	2	1	1	0	0	4	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Wadjemup	Wadjemup Road	TBA	Lighthouse Out Buildings	N	Fibre cement eaves lining	Perimeter of out building	2	1	1	0	0	4	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Wadjemup	Wadjemup Road	TBA	Lighthouse Out Buildings	N	Fibre cement ceiling lining	Throughout out building	2	1	1	0	0	4	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Wadjemup	Wadjemup Road	WADJ-TBA	Observation Tower	N	Molded fibre cement cable pit	South side of Tower	3	1	1	1	1	7	A3	20/09/2017	Coffey Environments	ENAUPTERT 02892AA	2		Sep-20
Wadjemup	Wadjemup Road	WADJ-WHSST	Disused Signal Station	N	Molded fibre cement cable pit	Rear of building	2	1	1	2	1	7	A3	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Wadjemup	Wadjemup Road	WADJ-WHSST	Disused Signal Station	N	Fibre cement ceiling and wall linings	Throughout building	2	1	1	0	0	4	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Wadjemup	Wadjemup Road	WADJ-WPLOB	Lighthouse Keepers Cottage	N	Small corrugated fibre cement fence	Adjacent Garage	3	1	1	2	1	8	A3	20/09/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Wadjemup	Wadjemup Road	WADJ-WPLOB	Lighthouse Keepers Cottage	N	Small corrugated fibre cement external wall cladding	Garage	3	1	1	2	1	8	A3	20/09/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Wadjemup	Wadjemup Road	WADJ-WPLOB	Lighthouse Keepers Cottage	N	Molded fibre cement cable pit	North side of cottage	3	1	1	1	1	7	A3	20/09/2017	Coffey Environments	ENAUPTERT 02892AA	2		Sep-20
Wadjemup	Wadjemup Road	WADJ-WPLOB	Lighthouse Keepers Cottage	N	Molded fibre cement vent pipes	North side of cottage	3	1	1	0	0	5	A4	20/09/2017	Coffey Environments	ENAUPTERT 02892AA	2		Sep-20
Wadjemup	Wadjemup Road	WADJ-WPLOB	Lighthouse Keepers Cottage	N	Fibre cement wall cladding	Enclosed verandah of Cottage	2	1	1	0	0	4	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Wadjemup	Wadjemup Road	WADJ-WPLOB	Lighthouse Keepers Cottage	N	Fibre cement wall lining	Bathroom	1	1	1	1	0	4	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Wadjemup	Wadjemup Road	WADJ-WPLOB	Lighthouse Keepers Cottage	N	Fibre cement wall cladding	Enclosed verandah of Cottage	2	1	1	0	0	4	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Wadjemup	Wadjemup Road	WADJ-WPLOB	Lighthouse Keepers Cottage	N	Fibre cement ceiling and wall lining	Enclosed back verandah of Cottage	1	1	1	0	0	3	A5	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Wadjemup	Wadjemup Road	WADJ-WPLOB	Observation Tower	N	Molded fibre cement cable sleeve	West side of Tower	1	1	1	1	1	5	A4	43025	Coffey Environments	ENAUPTERT 02892AA	2		43390
Wadjemup	Wadjemup Road	WADJ-WPLTH	Lighthouse	N	Molded fibre cement pipe in ground	Adjacent water tank structure	1	1	1	1	0	4	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Wadjemup	Wadjemup Road	WADJ-WPLTH	Lighthouse	N	Fibre cement external wall cladding	Out building adjacent lighthouse	2	1	1	0	0	4	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Wadjemup	Wadjemup Road	WADJ-WPLTH	Lighthouse	N	Fibre cement eaves lining	Perimeter of out building	2	1	1	0	0	4	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18
Wadjemup	Wadjemup Road	WADJ-WPLTH	Lighthouse	N	Fibre cement ceiling lining	Throughout out building	2	1	1	0	0	4	A4	17/10/2017	Coffey Environments	ENAUPTERT 02892AA	2		Oct-18

GROUP (AREA/ SUBURB)	ADDRESS 1	SITE ID (Maximo Ref)	KNOWN AS	Site Ref	SAMPLE DESCRIPTION	SAMPLE LOCATION	Coffey Environments Risk Assessment							Asbestos Management						
							Asbestos Fibre Type	Treatment Surface	Product Type	Condition	Likelihood of Disturbance	Risk Score	Action Rating	Inspection Date	Asbestos Consultant	Report Reference Number	Inspection Type	Labelled Y/N	Re-inspection Due (as required by [NOHSC:2018 (2005)])	